

# Safety Alert 018

---

## Title: Novacomet branded BP1803 LPG gas regulator manufactured by Clesse Industries - Recall

Date issued: 25 January 2016

***This Safety Alert provides guidance to Gas Safe Registered businesses/engineers about a product recall issued by Clesse (UK) Ltd, for their LPG regulator product family BP1803***

### Introduction

Clesse Industries, manufacturer of LPG gas regulator brand Novacomet has issued an immediate product recall on LPG regulator family BP1803.

### Background

Used with propane and butane LPG cylinders, the recall involves all directly cylinder mounted, wall mounted single cylinder and two cylinder manual changeover versions manufactured between June 2010 and September 2015.

### Action Required

Using the identification process, if your regulators are part of the recall, used for outdoor applications and fall within the specified dates, register your details using one of the methods detailed below. If you are unsure how to identify your product, visit the following website [www.clessesafetynotice.com](http://www.clessesafetynotice.com) or contact Clesse's Recall Help Line. Following successful identification and registration, Clesse Industries will process and supply replacement BP1803 regulators free of charge, as well as contribute to the cost of the product exchange that falls within this recall.

### LPG Distributors and Merchants

Please ensure that any remaining stocks dated between June 2010 and September 2015 are documented for replacement using the registration website as detailed below.

## Installed Gas Regulators

Holiday and residential parks, LPG engineers and private individuals can identify any installed regulators using the pictures below and check whether the product is marked with “Novacomet BP1803” and lists a manufacturing date between June 2010 and September 2015. Gas installers and Gas Safe registered businesses/engineers and Residential or Holiday Park site owners that may have many regulators fitted can contact the Recall Help Line and Clesse will assist in scheduling a replacement program.


**Registration website**  
**Recall Help Line**

[www.clessafetynotice.com](http://www.clessafetynotice.com)  
0800 088 5545

## Identification

The recalled models requiring exchange will display “BP1803” and dates between June 2010 and September 2015. Regulators displaying any other model number or dates ARE NOT part of the recall.

1. Regulator model BP1803 mounted horizontally on UK and Irish propane cylinders, and vertically wall mounted as single cylinder and manual changeover kits. Some models may also be installed as an “in-line” regulator with a ¼” inlet connection.
2. Label identification shown in images 2a to 2d with model number BP1803 and date displayed as MM/YY as in pictures 3a to 3b.



For more information regarding why Clesse Industries are undertaking this recall and for further useful information visit [www.clessesafetynotice.com](http://www.clessesafetynotice.com)

-o0o-

Page 2 of 2  
SAFETY ALERT xxx

Gas Safe Register® has used its best efforts in the production of this information, but makes no warranty about the content and will not be held liable under any circumstances for any direct or indirect damages resulting from the use of this information. This document may not be reproduced in whole or in part without the consent of Gas Safe Register® other than for personal reference purposes only. This document is uncontrolled when printed, please visit: <https://www.gassaferegister.co.uk/sign-in/>, login and visit the Technical Information area for the controlled (current) copy. © Capita Gas Registration and Ancillary Services Ltd, 2011.